
1/16

# FIG.1






### 2/16


### F I G . 2

### LIGHT DOES NOT PASS



POLARIZATION AXIS OF FIRST POLARIZING PLATE 14 ⊥ POLARIZATION AXIS OF SECOND POLARIZING PLATE 15 (OPTICAL AXIS OF DOUBLE REFRACTION IS COAXIAL WITH POLARIZATION AXIS OF FIRST POLARIZING PLATE 14)

F I G . 3



4/16

FIG.4A





FIG.4B



5/16

FIG.5A




FIG.5B




FIG.5C





FIG.6



F I G . 7




FIG.8





FIG.9



9/16

FIG.10A




FIG.10B






FIG.10C



10/16

FIG.11



11/16

FIG.12A





FIG.12B



12/16

FIG.13A




FIG.13B





FIG.13C



13/16

FIG.14A






FIG.14B




## FIG.15



15/16

FIG.16

LIGHT DOES NOT PASS



POLARIZATION AXIS OF FIRST POLARIZING PLATE 560  $\perp$  POLARIZATION AXIS OF SECOND POLARIZING PLATE 570

16/16

